

1. CUTS THROUGH A DIAGONAL BACKER IN THE PANEL WIDTH REQUIRE REMOVAL OF THE DIAGONAL BACKERS AND THEY ARE NOT ABLE TO BE REPLACED IN ANOTHER LOCATION

